


Preliminary Findings of the Rubber Dam Inspections

February 2014

Overview of Findings

- College Heights: Minor splits in rubber. Dam in good condition.
- Hickory: No fin separation. Repaired plug with new patch.
- Lower Day: Some fin separation. Significant split in outer rubber “fold”. Reinforcing patch to be applied on 2/25. Regular inspection recommended.
- RP-3: Minor splits in rubber and mild corrosion of metal frame.
- Turner: Significant split in outer rubber “fold”. Has not penetrated through reinforcing layer. Reinforcing patch applied. Regular inspection recommended.





2/2/2015 12:05

Vector Control Services Repayment

Vector Control Costs

Date	Amount
July 2011 – December 2011	\$6,412
CY 2012	\$8,242
CY 2013	\$15,807
January 2014 – June 2014	\$8,860
July 2014 – December 2014	~\$15,000

- Total July 2011 through June 2014: \$39,321
- FY 2014/2015 Vector Control Budget: \$18,800