



SUBSIDENCE CONTOURS AND GROUND FISSURES IN THE CHINO AREA

Source: OBMP Phase I Report, Figure 2-24

TOM DODSON & ASSOCIATES
 Environmental Consultants

FIGURE 4.5-20