








Optimum Basin Management Program  
Chino Basin Watermaster

Legend

-  Fall 1933 Groundwater Elevation (ft-msl)
-  Fault
  - Dashed Where Approximate
  - Dotted Where Concealed
  - Queried Where Uncertain
  - Large Dots Where Groundwater Barrier (Suspected Fault)
-  Management Boundaries
-  Stream System
-  Hydrologic Chino Basin
-  Recharge Basins
-  Bedrock

Management Zone Index Map




Figure 2-20  
Fall 1933  
Groundwater Elevation Map

**WE** WILDERMUTH  
ENVIRONMENTAL, INC.

Date: August 19, 1999

