

Optimum Basin Management Program
Chino Basin Watermaster

Legend

- Groundwater Elevation Difference (feet)
- Fault
 - Dashed Where Approximate
 - Dotted Where Concealed
 - Queried Where Uncertain
 - Large Dots Where Groundwater Barrier (Suspected Fault)
- Management Boundaries
- Stream System
- Hydrologic Chino Basin
- Recharge Basins
- Bedrock

Management Zone Index Map




Figure 2-21
Groundwater Level Change
between Fall 1933 and Fall 1997
with Management Zone Boundaries

WE WILDERMUTH
ENVIRONMENTAL, INC.

Date: August 19, 1999