

Optimum Basin Management Program
Chino Basin Watermaster

Legend

- Groundwater Elevation Difference (feet)
- Water Service Area Boundary
- Estimated Area of Regional Subsidence (Klienfelder 1993)
- Rivers & Streams
- Fault
 - Dashed Where Approximate
 - Dotted Where Concealed
 - Queried Where Uncertain
 - Large Dots Where Groundwater Barrier (Suspected Fault)
- Bedrock
- Hydrologic Chino Basin
- Recharge Basins

Management Zone Index Map





Figure 2-22
Groundwater Level Change
between Fall 1933 and Fall 1997
with Water Service Areas

WE WILDERMUTH
ENVIRONMENTAL, INC.

Date: August 19, 1999



0 1 2 3 4 Miles