



Recharge Improvements Recommended by the RMP Steering Committee
(Project number shown is for locational reference from Table 6-1)

Recharge Basins
(Symbolized by Recharged Water Type)

- Storm, Imported and Recycled Water
- Storm and Imported Water
- Storm Water
- Incidental Stormwater Only

Other Features

- OBMP Management Zones
- Streams, Rivers, and Channels

Geology

Water-Bearing Sediments

- Quaternary Alluvium

Consolidated Bedrock

- Undifferentiated Pre-Tertiary to Early Pleistocene Igneous, Metamorphic, and Sedimentary Rocks

Faults

- Location Certain
- Location Concealed
- Location Approximate
- Location Uncertain
- Approximate Location of Groundwater Barrier



Produced by:
WILDERMUTH
 ENVIRONMENTAL INC.
 23692 Birtcher Drive
 Lake Forest, CA 92630
 949.420.3030
 www.wildermuthenvironmental.com

Author: MJC
 Date: 1/21/2013
 Name: Figure_6-1



CHINO BASIN WATERMASTER
 Authority of Basin Management
 2012 Recharge Masterplan Update

Recharge Improvements Recommended by the RMP Steering Committee

Figure 6-1