



WELLS WITH ONE OR MORE HISTORICAL TRICHLOROETHENE VALUES ABOVE 1/2 THE EXISTING MCL

TOM DODSON & ASSOCIATES
Environmental Consultants

FIGURE 4.10-3

Source: OBMP Phase I Report, Figure 2-49