



4-227



### Legend

- Groundwater Elevation Difference (feet)
- Fault
  - Dashed Where Approximate
  - Dotted Where Concealed
  - Queried Where Uncertain
  - Large Dots Where Groundwater Barrier (Suspected Fault)
- Management Boundaries
- Stream System
- Hydrologic Chino Basin
- Recharge Basins
- Bedrock



**GROUNDWATER LEVEL CHANGE BETWEEN FALL 1933 - FALL 1997  
WITH MANAGEMENT ZONE BOUNDARIES**

**TOM DODSON & ASSOCIATES**  
Environmental Consultants

**FIGURE 4.5-17**

Source: OBMP Phase I Report, Figure 2-21