

Optimum Basin Management Program  
Chino Basin Watermaster

Legend

- Fall 1997 Groundwater Elevation (ft-msl)
- Fault
  - Dashed Where Approximate
  - Dotted Where Concealed
  - Queried Where Uncertain
  - Large Dots Where Groundwater Barrier (Suspected Fault)
- Rivers & Streams
- Management Zone Boundary
- Hydrologic Chino Basin
- Recharge Basins
- Bedrock

Management Zone Index Map




Figure 2-19  
Fall 1997  
Groundwater Elevation Map

**WE** WILDERMUTH ENVIRONMENTAL, INC.

Date: August 19, 1999