

## IEUA GWR Basin Maintenance History and Plan

GRCC Feb 26, 2019

Recharge Basin:	FY12-13		FY13-14		FY14-15		FY15-16		FY16-17		FY17-18		FY18-19		FY19-20		
	July-Dec.	Jan.-June	July-Dec.	Jan.-June	July-Dec.	Jan.-June	July-Dec.	Jan.-June	July-Dec.	Jan.-June	July-Dec.	Jan.-June	July-Dec.	Jan.-June	July-Dec.	Jan.-June	
College Heights E.																	
College Heights W.													Rubber Dam Patch September				
Upland																	
Montclair #1																	
Montclair #2																	
Montclair #3																	
Montclair #4																	
Brooks	SC						SR - Dec. 2015						Silt Removal October				
8th Street #1	SR						SR - Nov 2015					SR June/July			LT Improvement		
8th Street #2 (7th St.)							SR - Jun 2015					SR June/July					
Ely #1	SR														Infiltration Restoration		
Ely #2	SR - Dec 2012														Infiltration Restoration		
Ely #3	SR - Nov 2012																
Grove																	
Turner #1		SR - Oct. 2013					SR - Sept 2015					Rdam patch March			Infiltration Restoration		
Turner #2		SR - Sept. 2013													Infiltration Restoration		
Turner #3		SR - Sept. 2013							SR- DEC 2016			Slope repair Jan 2018			Infiltration Restoration		
Turner #4a		SR - Aug. 2013							SR- DEC 2016			Slope repair Jan 2018			Infiltration Restoration		
Turner #4b															Infiltration Restoration		
Turner #4c																	
Lower Day															Berm repair		
Etiwanda Sp. Gr.																	
Etiwanda Debris Basin															Infiltration Restoration		
Victoria		SR - Oct - Nov. 2013						SR-June	SR-AUG 2016			SR June/July	Solar Bee installation		Infiltration Restoration		
San Sevaine #1															Heavy Weeding/ Silt Reduction		
San Sevaine #2																	
San Sevaine #3																	
San Sevaine #5		Berm Access - Dec. 2013								Soil stockpile reduction (SBCFCD)							
Jurupa	Conservation Berm Reshape and								Upper Channel Cleaning/Pump		Slope, berm, road repairs (SBCFCD)	/Pump cleaned				Access Ramp	
Banana		SR - Sept. 2013									SR- July				Infiltration Restoration		
Hickory		SR - Sept. 2013									SR- June	Rdam patch March			Infiltration Restoration		
RP3 #1a & 1b	SR - Nov 2012							SR-June	SR -JULY 2016						Infiltration Restoration		
RP3 Cell 2																	
RP3 #3a & 3b	SR - Nov 2012														Infiltration Restoration		
RP3 #4a & 4b	SR - Nov 2012									SR-SEPT 2016					Infiltration Restoration		
Declez											SR-NOV 2016						

PLANNED IN RED