



IEUA GWR Basin Maintenance Update to the GRCC

Brent Ritzinger
RW/GWR O&M Specialist
August 27th, 2024

GWR Operations & Maintenance Activities


- Ely 3 Level Transmitter replacement
- MWD turnout maintenance/repairs
- Rip Rap placement in San Sevaine 5
- Infiltration Restoration Projects
 - RP3, Declez and 8th Street
- Turner 2 and 4A maintenance
- Vandalism
 - Brooks, Montclair 4 and RP3
- Upcoming infiltration restoration projects

LT Replacement – Ely 3

06/19/2024



MWD – CB-20 Additional Damage



MWD – CB-14 pilot system leak

05/20/2024



Rip Rap Placement in SS5

08/26/2024



Infiltration Restoration – RP3

07/25/2024



Infiltration Restoration – RP3

08/13/2024



Infiltration Restoration – RP3

08/13/2024



Infiltration Restoration – RP3



Distribution Channel Cleaning – RP3



Distribution Channel Cleaning – RP3

08/21/2024



Distribution Channel Cleaning – RP3

08/26/2024



Distribution Channel Cleaning – RP3

08/26/2024



Infiltration Restoration – Declez

08/12/2024



Infiltration Restoration – Declez

08/20/2024



Infiltration Restoration – Declez

08/26/2024



Infiltration Restoration – 8th Street

08/20/2024



Maintenance at Turner 4A

07/01/2024

Turner 3

Turner 4A



Maintenance at Turner 4A

07/01/2024



Maintenance at Turner 4A

07/08/2024 11:00



07/08/2024 11:02

Turner 2 Washout



Turner 2 Washout

08/26/2024



Turner 3

Turner 2

Turner 2 Washout

08/26/2024



Turner 4B

Turner 4A

Vandalism – Brooks



Vandalism – Wire Theft at Montclair 4



Vandalism – RP3 Fence Cuts



Vandalism – RP3 Fence Repairs



Upcoming Basin Cleanings

8/27/2024

